

## **Memory Control Error Code Guide**

Premium Electric Adjustable Height Base

Error Code	Protection	Situation	Buzzer Alert	Solution
0	Resetting	Press UP&DOWN buttons at the same time for 3 seconds. Continue pressing the buttons until both columns are in lowest position.	1 Beep	Keep pressing UP&DOWN buttons at the same time til hear 1 Beep from control box(TC).
E00	Incomplete reset	Reset incomplete. ex. release of any button while retracting	None	Keep pressing UP&DOWN buttons at the same time til hear 1 Beep from control box(TC).
E01	Overuse protection (10% duty cycle)	The protection will be activated after operating continuous use for 1min.	E01 flashes for 5 secs. Long 3 beeps.	Stop playing the desk for 2 mins at least, it needs calm down for a while after working too hard.
E02	Unbalance protection	Protection mode comes into play when the height of the gap is over 10mm between the two columns during the system operation.	E02 flashes for 5 secs. 2 beeps.	Reset the desk.
E03	Anti-collision (Basic function in control box)	Collision detection during operation.	E03 flashes for 5 secs. No beep, desk reverses for 40mm.	Remove the obstacle.  Desk can be operated again after it stops from reversing.
E04	Anti-collision T-touch Protection	<ol> <li>Collision detection during operation.</li> <li>T-touch does not fixed well.</li> </ol>	E04 flashes for 5 secs. No beep, desk reverses for 30mm.	Remove the obstacle or fix t-touch well.  Desk can be operated again after it stops from reversing.
E11	Motor(M1) overcurrent	Loading over 80kg on one side (M1) of the desk     Internal transmission of column is jammed	E11 flashes for 5 secs. 5 beeps.	Check the load on the desk if one side overloaded. If no overload issue, please contact supplier for column inspection.
E12	Motor(M2) overcurrent	Loading over 80kg on one side (M2) of the desk     Internal transmission of column is jammed	E12 flashes for 5 secs. 5 beeps.	
E21	Motor(M1) no Hall sensor signal	One column moves and the other does not. (the working column does not move)	E21 flashes for 5 secs. 2 beeps.	Check the cable status if any damage, reset before operating.  Contact supplier for motor or motor cable replacement.
E22	Motor(M2) no Hall sensor signal	One column moves and the other does not. (the working column does not move)	E22 flashes for 5 secs. 2 beeps.	
E31	Motor(M1) No current	(M1) Motor wire not correctly connected to the control box. One column is not moving (Another column might slightly shakes)	E31 flashes for 5 secs. 4 beeps.	Check all the plugs if connecting well. Replug all the plugs are recommended.
E32	Motor(M2) No current	(M2) Motor wire not correctly connected to the control box. One column is not moving (Another column might slightly shakes)	E32 flashes for 5 secs. 4 beeps.	